

Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
QUARRY LANE	o/s 60	Damaging	Damaging 3rd party boundary wall	Acer pseudoplatanus	Plant in grass verge O/S 49 (opposite felled tree, relocated as f/w very narrow)	Acer campestre 'Elegant'
QUARRY LANE	o/s 64	Damaging	3rd party wall damage and substantial f/w mounding	Acer pseudoplatanus	Plant in grass verge O/S 53 (opposite felled tree, relocated as f/w very narrow)	Acer campestre 'Elegant'
QUARRY LANE	o/s 62	Damaging	Buttress roots in c/w, will by unacceptably damaged upon resurfacing	Acer pseudoplatanus	Plant in grass verge O/S 51 (opposite felled tree, relocated as f/w very narrow)	Acer campestre 'Elegant'